

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE

Cashier: JESSE WOHRMEYER

Repair Order # 9940010633

Invoice # 37427

Sold to GAY, EVAN (2015656)
PO BOX 54382
CINCINNATI, OH 45254
Home Phone 513-201-5656

Invoice Date 2/19/14
Date In 12/12/13
Promised 0/ 0/ 0
Closed Out 2/19/14

Yr Make	Model	Color	Class	Plate #	VIN	Key Board#	Hrs/Odom
==	====	=====	=====	=====	=====	=====	=====
75 BMW	R75/6	COPPER			4940925		0

Job: BRAKE LINES

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE INSTALL NEW FRONT BRAKE LINE

	Part #/Labor Code	Description	Src	Cat	Tech	Hrs/Qty	Total
Parts	S-BM0028	BMW R/6 BRAKE LINE	SE	OTP		1	66.95
	12502	CASTROL GT LMA DOT4	PU	OIL		1	9.95
	189099107	BRAKE AND PARTS CLEANER	WU	OTP		1	9.95
	189099107	BRAKE AND PARTS CLEANER	WU	OTP		1	9.95
Labor		REPLACE BRAKE LINE			DW	6.00	40.50
Supplies							.81
Job Subtotal \$		138.11					

Job: RESEAL ENGINE AND TRANSMISSION

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE RESEAL THE ENGINE AND TRANSMISSION

	Part #/Labor Code	Description	Src	Cat	Tech	Hrs/Qty	Total
Parts	11111338342	MAIN SEAL 100X80X10	BG	BHP		1	32.95
	11131338427	OIL PAN GASKET	BG	BHP		1	11.95
	11111255001	BASE GASKET 1970-75	BW	BHP		2	13.00
	11321250267	PUSH ROD SEAL	BW	BHP		4	21.00
	11121338716	CYL. HEAD GSKT.	BG	BHP		2	39.26
	11121338426	VALVE COVER GASKET	BW	BHP		2	15.90
	11141261193	SEAL 1970-75	BG	BHP		1	10.95
	11141255011	SEAL	BG	BHP		1	22.10
	11141265394	SEAL STRIP 3.2MM	BG	BHP		1	3.95
	11221262060	BOLT 11X1.5	BG	BHP		5	21.45
	11410552280	GASKET	BM	BHP		1	1.95
	11411335895	O-RING	BG	BHP		1	3.95
	23121232681	SEAL	BW	BHP		1	13.95
	21511230109	DUST BOOT	BG	BHP		1	9.95
	21521020109	SEAL	BW	BHP		1	6.95
	23121338726	OIL SEAL	BG	BHP		1	12.95
	189099107	BRAKE AND PARTS CLEANER	WU	OTP		1	9.95

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE
Repair Order # 9940010633

Invoice # 37427
Page 2

Sold to GAY, EVAN (2015656)

Invoice Date 2/19/14

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
=====	=====	===	===	=====	=====
13721254654	AIR TUBE RUBBER	BW BHP		2	27.90
26111242297	BOLT M 8X1	BG BHP		4	10.00
33172311098	GASKET	BG BHP		1	2.95
61138080160	SPEEDO CABLE BOOT	BG BHP		1	6.95
Labor	RESEAL ENGINE AND TRANS		DW	72.00	486.00
Supplies					8.00
Job Subtotal \$	793.96				

Job: CLUTCH DISK

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE INSTALL NEW CLUTCH DISK

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
=====	=====	===	===	=====	=====
Parts 21211250288	CLUTCH SPRING	BM BHP		1	150.95
21211236332	HD CLUTCH PLATE	BG BHP		1	87.95
Labor	INSTALL NEW CLUTCH DISK		DW	1.00	6.75
Supplies					.14
Job Subtotal \$	245.79				

Job: TIRES

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE MOUNT AND BALANCE FRONT AND REAR TIRES

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
=====	=====	===	===	=====	=====
Parts IRC-65	TUBE 350/400 X 18 T	PU TIR		1	13.95
IRC-68	TUBE 325/410,100/90-	PU TIR		1	12.95
0302-0722	CONTI CLASSIC ATTK 120/90R-18	PU TIR		1	150.95
0301-0435	CLSC ATTK 100/90-19	PU TIR		1	141.95
Labor	MOUNT AND BALANCE TIRES		DW	18.07	122.00
Supplies					2.44
Job Subtotal \$	444.24				

Job: POINT/CONDENSOR

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE INSTALL NEW SETS OF POINTS AND CONDENSOR

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
=====	=====	===	===	=====	=====
Parts 12111351564	CONDENSOR	BW BHP		1	17.95
12111243555	POINT SET	BG BHP		1	21.60

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE
Repair Order # 9940010633

Invoice # 37427
Page 3

Sold to GAY, EVAN (2015656)

Invoice Date 2/19/14

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
BP6ES	NGK SPARK PLUG	PU	PUA	2	5.90
LB05F	SPARK PLUG CAP	PU	OTP	2	5.90
01-114-1	PLUG WIRE COPPER PER FT.	PU	OTP	4	3.80
Labor	TIME ENGINE		DW	12.00	81.00
Supplies					1.62
Job Subtotal \$	137.77				

Job: BARS

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE REPLACE BARS

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts 0601-0169	R90S STYLE BAR	PU	PUA	1	104.95
32721237811	GRIP LEFT	BG	BHP	1	9.95
32731230037	BOOT	BW	BHP	1	4.25
32731236612	THROTTLE CABLE LOWBA	BM	BHP	2	32.78
32732324958	CLUTCH CABLE (56")	BG	BHP	1	35.95
32721232662	BUSHING	BG	BHP	2	9.90
32721230871	WASHER WAVE LEVER PIVOT /5/6	BW	BHP	2	3.10
Labor	REPLACE HANDLEBARS		DW	12.00	81.00
Supplies					1.62
Job Subtotal \$	283.50				

Job: SEAT LATCH

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE FIND A SEAT LATCH WITH WORKING LOCK AND KEY

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts 07119900811	5-SCREW	BG	BHP	3	2.25
52531236351	DUAL SEAT HINGE	BM	BHP	1	60.50
Labor	NEW SEAT LOCK		DW	3.00	20.25
Supplies					.41
Job Subtotal \$	83.41				

Job: BATTERY CABLES

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE REPLACE THE BATTERY CABLES

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE
Repair Order # 9940010633

Invoice # 37427
Page 4

Sold to GAY, EVAN (2015656)

Invoice Date 2/19/14

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	BCK-475473	BATTERY CABLE UPGRADE	EO	OTP	1	25.00
	46631233327	DECAL 750CC	BM	BHP	1	35.95
Labor		INSTALL NEW BATT CABLES		DW	2.00	13.50
Supplies						.27
Job Subtotal \$		74.72				

Job: SUB FRAME

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE REPLACE THE SUB FRAME.. IT IS BENT

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	8267240	AIRHEAD SUB FRAME	EY	BHP	1	160.95
	46621230798	RUBBER WASHER	BW	BHP	8	25.20
	63231352944	BASE	BM	BHP	1	2.95
	07119913016	BOLT M6X20	BG	BHP	2	3.90
Labor		REAR SUB FRAME		DW	9.00	60.75
Supplies						1.22
Job Subtotal \$		254.97				

Job: FRONT FORK SEALS

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
FRONT FORK SEALS ARE LEAKING PLEASE REPALCE.

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	31421230001	FORK SEAL	BG	BHP	2	17.90
	3609-0044	OIL FORK HIGH PERF 15W	PU	OIL	1	14.75
	07119936041	07119936042	BM	BHP	2	.08
	189099107	BRAKE AND PARTS CLEANER	WU	OTP	1	9.95
Labor		FRONT FORK SEALS		DW	6.00	40.50
Supplies						.81
Job Subtotal \$		83.99				

Job: FRONT WHEEL BEARINGS

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
FRONT WHEEL BEARINGS ARE BAD. PLEASE REPLACE.

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	0215-0625	BEARING KIT	PU	OTP	1	41.95
	36311231248	SPACER 7.15	BM	BHP	1	4.66

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE
Repair Order # 9940010633

Invoice # 37427
Page 5

Sold to GAY, EVAN (2015656)

Invoice Date 2/19/14

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Labor	FRONT WHEEL BEARINGS		DW	6.00	40.50
Supplies					.81
Job Subtotal \$	87.92				

Job: CHANGE ALL FLUIDS

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE CHANGE ALL THE FLUIDS

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts 20W50D	20W50 CASTROL OIL DRUM	PU OIL		3	20.85
HF161	HIFLOFILTRO OIL FILT	PU PUA		1	6.95
11421338600	9-GASKET	BG BHP		1	2.95
07119963300	GASKET RING	WU BHP		3	2.85
07119963200	SEAL RING	BG BHP		3	3.15
07119963130	SEAL RING	BM BHP		2	1.00
00376	MTX SYN RACE GEAR OI	PU OIL		1	13.50
R.HDPG6	HD PLATINUM 6SPD 75W140 GL5	SO OIL		1	19.95
Labor	REPLACE FINAL DRIVE FLUID		DW	2.00	13.50
Supplies					.27
Job Subtotal \$	84.97				

Job: REPACK SWING ARM BEARINGS

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE REPACK SWING ARM BEARINGS

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts 31412000331	SEAL	BM BHP		2	9.90
Labor	REPACK SWINGARM BEARINGS		DW	3.00	20.25
Supplies					.41
Job Subtotal \$	30.56				

Job: FIX HEADLIGHT

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:

Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts 61321358193	RELAY {SR9725}	BG BHP		1	23.95
194BP	EKO BULBS	KO OTA		1	3.95
Labor	FIX HEADLIGHT		DW	3.00	20.25
Supplies					.41
Job Subtotal \$	48.56				

CADRE CYCLE
11121 DEERFIELD RD. UNIT "D"
CINCINNATI , OH 45242
513-522-7300

REPAIR ORDER INVOICE
Repair Order # 9940010633

Invoice # 37427
Page 6

Sold to GAY, EVAN (2015656)

Invoice Date 2/19/14

Job: SPEEDO

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:
PLEASE HAVE SPEEDO RESET

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	MISCITEM	MECHANICAL SPEEDO M/C	WV	OTP	1	255.00
Labor		INSTALL SPEEDO		DW	6.00	40.50
Supplies						.81
Job Subtotal \$	296.31					

Job: COVER

Yr: 75 Make: BMW Model: R75/6 Color: COPPER Class:

	Part #/Labor Code	Description	Src Cat	Tech	Hrs/Qty	Total
Parts	4001-0148	COVER DEFENDER 500 XL	PU	OTA	1	69.95
Job Subtotal \$	69.95					

Job	Parts	Labor	Sublet	Other	Total of all Jobs	
Breakdown ->	2,051.43	1,087.25	.00	20.05	3,158.73	

"ESTIMATE RIGHTS"		"STORAGE FEES"		Before Tax Total	
YOU HAVE THE RIGHT TO AN ESTIMATE		UPON COMPLETION OF WORK		3,158.73	
IF THE EXPECTED COST OF REPAIRS OR		IF NOT PICKED UP AFTER		Sales Tax 213.21	
SERVICES WILL BE MORE THAN TWENTY-		07 DAYS, STORAGE FEE OF		=====	
FIVE DOLLARS. INITIAL YOUR CHOICE.		\$15.00 PER DAY WILL BE		Repair Order Total 3,371.94	
[] WRITTEN ESTIMATE		INCURRED UNLESS OTHER		Less Previous Deposits 2,000.00	
[] ORAL ESTIMATE		ARRANGEMENTS HAVE BEEN		* * Total Amount Due 1,371.94	
[] NO ESTIMATE		MADE IN ADVANCE.		VISA/MC Tendered 1,371.94	

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG
WITH THE NECESSARY MATERIALS. AND HEREBY GRANT YOU AND/OR
YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN
DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSE
OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN IS
HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMMOUNT
OF REPAIRS THERETO. NOT RESPONSIBLE FOR LOSS OR DAMAGE
TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE,
THEFT, OR CAUSES BEYOND OUR CONTROL INCLUDING PARTS ETC.
THAT FALL OFF IN THE COURSE OF TEST DRIVING.X

Wednesday, February 19th, 2014 2:01 pm

Customer Copy
Beemers Uber Alles

9248 Mike Garcia Drive
Manassas, VA, 20109
(571) 318 2472
beemersuberalles.com

Bill To: R75/6
Evan Gay

Item Name	Attribute	Size	Orig Price	Disc %	Type	Qty	Price	Ext Price	Tax
labor			\$90.00			2.25	\$90.00	\$202.50	

Subtotal: \$202.50

Local Sales Tax 0 % Tax: + \$0.00

RECEIPT TOTAL: \$202.50

Credit Card: \$202.50 XXXX3116 Visa
Reference # 0000006002

Entry: Swiped

Auth=06589C
Merchant #***34789

Signature _____

I agree to pay above amount according to card issuer
agreement (merchant agreement if credit voucher).

Adjust valves.
Adjust point gap.
Adjust timing.
Adjust carbs.
Rewire High beam indicator.
Mileage out 94

Ride safely.



1628

Customer Copy
Beemers Uber Alles
9248 Mike Garcia Drive
Manassas, VA, 20109
(571) 318 2472
beemersuberalles.com

Bill To: R75/6
Evan Gay

Item Name	Attribute	Size	Orig Price	Disc %	Type	Qty	Price	Ext Price	Tax
Fork springs			\$92.95			1	\$92.95	\$92.95	T
Fork oil 7w	Bell Ray		\$14.75			0.5	\$14.75	\$7.38	T
seal ring			\$1.99			2	\$1.99	\$3.98	T
crush ring			\$0.64			2	\$0.64	\$1.28	T
Fork gasket			\$0.89			2	\$0.96	\$1.92	T
Drive shaft boot			\$20.70			1	\$20.70	\$20.70	T
Drive shaft bolt			\$1.58			4	\$1.58	\$6.32	T
Mobil1 75w90			\$10.99			0.25	\$10.99	\$2.75	T
labor			\$90.00			4	\$90.00	\$360.00	

Subtotal: \$497.28

Local Sales Tax 6 % Tax: + \$8.24

RECEIPT TOTAL: \$505.52

Credit Card: \$505.52 XXXX3116 Visa
Reference # 0000006001

Entry: Swiped

Auth=00968C
Merchant #***34789

Signature _____
I agree to pay above amount according to card issuer
agreement (merchant agreement if credit voucher).

R75/6

Replace fork springs.
Change fork oil.
Adjust points.
Checkvalves.
Adjust carbs sync.
Replace drive shaft boot.
Mileage out: 653

Ride safely.



1968